

Mini-Check Non-Iron Button-Down Shirt. RH66

PRODUCT MEASUREMENTS

	VC		M		м	0.74	3XL	41/1
	XS	5	М	L	XL	2XL	3AL	4XL
Chest Width	20	21 1/2	23	24 1/2	26	27 1/2	29 1/2	31 1/2
Sleev e Length	33 3/4	34 1/2	35 1/4	36	36 3/4	37 1/2	38 1/4	39
Body Length at Back	30	31	32	33	34	35	35 1/2	36
Pocket Height	5 1/4	5 1/4	5 1/2	5 1/2	5 1/2	5 1/2	5 1/2	5 3/4
Pocket Width	4 3/4	4 3/4	5	5	5	5	5	5 1/4
Neck	16 1/2	16 1/2	17	17 1/2	18 1/2	19 1/4	20	20 3/4

CHEST WIDTH SLEEVE LENGTH

Measured across the chest one inch below armhole when laid flat.

Start at center of neck and measure down shoulder, down sleeve to hem.

BODY LENGTH AT BACK POCKET HEIGHT

Measured from high point shoulder to finished hem at back.

Measure from top to bottom at center.

POCKET WIDTH NECK

Measure from side to side at top edge.

Measured from center of button to center of buttonhole.